




Cleanroom Gowning Procedure

(Non-sterile)



1. Wash Hands Thoroughly
2. Take a Few Steps Over a Tacky Mat
3. Don Disposable Booties (*Shoe Covers*)
4. Put on Donning Gloves
5. Apply Bouffant (*beard covers for users with facial hair*)
You can enter the gowning area.
6. Don Hood, Hood should completely cover your Bouffant.

7. Apply Face Mask.
8. Don Coverall
9. Don Cleanroom Booties
10. Don Goggles or Shield
11. Put on Cleanroom Gloves
12. Walk Over Tacky Mat.
Now, you can enter the cleanroom.